

Good day IRWIN AVE. Residents

I am John F of 33 Irwin and will be going before town counsel on sept. 16, 2024. All are welcome to join me in fighting to have our driveway entrances done properly. I personally have a 19 foot driveway and the town says its only 16 feet with a curb entrance of 13 feet because of curb slopes. I have attached a picture of my driveway where it shows the incorrect entry size as well right bellow it another house on Irwin where the driveway was poured properly and the full width of there driveway is the entry size of the curb opening and then the slopes start. I will be around to discuss this with you and if you unable to attend the meeting we can fill out the bottom of this form and I will represent all of us to try and get this rectified.



Picture above with incorrect entry vs picture bellow with correct entry size



ADDRESS PRINT NAME

DRIVEWAY SIZE AND ENTRY SIZE

SIGNATURE

Please consider the environment before printing this email.

This communication, including any attachments, is intended only for the use of the addressee(s) to this email and is confidential. If you are not an intended recipient or acting on behalf of an intended recipient, any review, disclosure, conversion to hard copy, dissemination, reproduction or other use of any part of this communication is strictly prohibited. If you receive this communication in error or without authorization, please notify the originator immediately and remove it from your system.

From: John Fraser

Sent: Monday, September 9, 2024 5:11 AM
To: McBeth, David < dmcbeth@essex.ca>
Subject: Re: Property stake for 33 Irwin

WARNING: This email originated from someone who is not sending from a Town of Essex email address. Reply only if you recognize the senders email address. Do not click links or open attachments unless you recognize the sender, the senders email address and know the content is safe.

Good morning David

Just to follow up on this email the property stake was not put back in before the neighbors driveway was done the distance from my sidewalk to the property stake is 19'10.5" and now her driveway is 2.5 inches on my property can you advise why this happened as I gave plenty of notice and pictures about the property stake also how you plan to rectify this issue

Thank you

On Wed, Jun 12, 2024, 10:13 a.m. John Frase

vrote:

Good morning Dave

Attached are pictures of the property stake between my house 33 Irwin and 37 Irwin. It is no longer there it was dug up by construction, I also believe the one between me and 29 Irwin was also dug up but I have no pictures of it.

From:		
Sent:	Monday, September 9, 2024 11:01 AM Fraser, John Fwd: Property stake for 33 Irwin 058_line_9bae9502-1e3a-48a3-ba5e-34ed9cd44185.png	
To:		
Subject:		
Attachments:		
	You have not previously corresponded with this so	ender.
Please exercise caution	opening attachments or clicking links and report emails with the "Re or PhishAlarm button in Outlook.	port Suspicious" button in this banner
		Report Suspicious
From: McBeth, Davi Date: Mon, Sept 9, 2 Subject: RE: Propert To: John Fraser	d < <u>dmcbeth@essex.ca</u> > 024, 9:02 a.m.	
John,		
	he contractor's list of deficiencies to rectify. Once the bar is burther direction will be given to the contractor at that time.	ack in place, the driveway location
Thank you.		





Regards,


David McBeth, C.E.T. Manager, Capital Works & Asset Management | Infrastructure Services


P: 519.776.7336 ext. 1113 | F: 519.776.8811 E: <u>dmcbeth@essex.ca</u> | <u>www.essex.ca</u> 33 Talbot Street S. Essex, ON N8M 1A8














LEFT SIDE OF DRIVEWAY 8" SHORT RIGHT SIDE 2 FEET SHORT SHOWN BY TAPE MEASURE

